


E-50-3NA



Д-500, Ш-474, В-820, мм.



L-500, W-474, H-820, mm.

Інструкція збірки
Assembly instruction

1

«E-50-3NA»





№	довжина(мм) length(mm)	ширина(мм) width(mm)	кількість quantity
1	704*	458	1
2	704*	458	1
3	458**	500*	1
4	468*	74	2
5	384*	68	2
6	384*	164	4
7	442*	68	1
8	442*	164	2
9	140**	496**	1
10	285**	496**	2
11	410	384	2
12	718	248	2
13	442	405	1



Важливо! Перед свердлінням отворів переконайтеся, що правильно обрали розташування ручок, і використовуйте відповідний інструмент.




Important! Before drilling holes, make sure you have chosen the correct handle placement and use the appropriate tools.

1.






3

2.









4

3.




5



4.



6

5.

- H 
- D 3,5x16 x12 
- B3 
- A2 30mm x12 
- L6 L=400MM x3 
- Y1 x6 



7

