


Колекція НС «П50-3+1»

Collection NS «P50-3+1»






Д-500, Ш-540, В-2070, мм.

L-500, W-540, H-2070, mm.











Інструкція збірки
Assembly instruction

«П50-3+1»/«P50-3+1»





№	довжина(мм) length(mm)	ширина(мм) width(mm)	кількість quantity
1	500*	540**	1
2	2050*	520	1
3	2050*	520	1
4	468*	520	1
5	468*	510	3
6	468**	64	5
7	494**	1316**	1
8	494**	196**	3
9	384*	100	6
10	443*	100	3
11	440	405	3
12	2000	496	1






1.













2.



3.













4.



5. x3

 x6	 x12	 x12	 x3
 x6	 x6	 x12	



7

